



**PALADIN**<sup>™</sup>  
POWERFUL ATTACHMENT TOOLS

Division of  
**IES** | INTERNATIONAL  
EQUIPMENT  
SOLUTIONS

# Service Bulletin

January 23<sup>rd</sup>, 2013

Bulletin No. **SB-009**

**Affected Models:** 30272 - \*\*\*\* Bradco Ground Shark

**Serial Numbers:** All units received prior to January 23<sup>rd</sup> 2013

## Summary:

Gearboxes on the Ground Shark may have been overfilled during assembly.

## Detail:

In working with our supplier, we have found that the proper oil fill level for the gearbox on a Ground Shark Extreme Duty Brush Cutter is **2.5 – 2.66 quarts (80-85 ounces)**

**The operators/parts manual that was shipped with the units showed a fill level of 3.75 quarts, this is incorrect and does not allow enough room for expansion while operating.**

If you would like an updated owners/parts manual please contact your Paladin Customer Service representative and one will be sent to you.

David Ellison  
Technical Service Manager  
734-222-3686

Jason Patterson  
Technical Service Coordinator  
734-214-2076

Scott Rouster  
Technical Service Specialist  
734-214-2077

Terry Thein  
Technical Service Specialist  
319-395-6170

---

The Power of Combined Excellence®



Corporate Headquarters:

2800 North Zeeb Road, Dexter, MI 48130 USA | 800-456-7100

[www.paladinattachments.com](http://www.paladinattachments.com)